

Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
DUNCAN ROAD	O/S 40	Dangerous	extensive stem wounding, poor specimen (TR: Felling-) - Kerbs absent, extensive stem wounding, multiple weak compression unions at crown break, poor specimen	Prunus Kanzan	Plant in new 800mm pit o/s 40 (same as felled tree)	Pyrus 'Chanticleer'
DUNCAN ROAD	O/S 109	No Tree to remove	TR: Felling, failed in winds 2/6/15, uprooted - Failed in wind 2/6/15, uprooting	Prunus cerasifera	Plant in existing pit o/s 109- 111	Crataegus laevigata 'Paul's Sc
DUNCAN ROAD	O/S 118	Damaging	TR: Felling Substantial f/w uplift/damage to network	Prunus Kanzan	Plant in new 800mm pit o/s 118-120 (relocated 2m to between 2 properties)	Pyrus 'Chanticleer'
DUNCAN ROAD	O/S 50	Damaging	TR: Felling Kerbs absent - cannot install without root damage	Prunus Kanzan	Plant in new 800mm pit o/s 50 (same as felled tree)	Pyrus 'Chanticleer'
DUNCAN ROAD	O/S 30	dangerous	TR: Felling Half crown lost, stem ripped out, unworthy of retention/poor specimen	Sorbus aucuparia sp	Plant in new 800mm pit o/s 30 (same as felled tree)	Pyrus 'Chanticleer'
DUNCAN ROAD	O/S 69	Dangerous	TR: Felling Basal Ganoderma sp. fungal fruiting bodies, old and new at multiple points around stem	Prunus Kanzan	Plant in new 800mm pit o/s 69 (same as felled tree)	Pyrus 'Chanticleer'
DUNCAN ROAD	0/5 81	Damaging	TR: Felling Kerbs displaced - cannot be rectified without root damage, potential 3rd party wall damage also	Prunus Kanzan	Plant in new 800mm pit o/s 81 (same as felled tree)	Pyrus 'Chanticleer'